

Groundwater Section

UNDERGROUND STORAGE TANK(S)

SITE NAME:

Oak Summit Farms

REGULATED

☒

NONREGULATED

☐

	<u>YES</u>	<u>NO</u>
RELEASE CONFIRMED:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
CLEAN-UP INITIATED:	<input type="checkbox"/>	<input type="checkbox"/>
TANK(S) REMOVED:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
RELEASE UNDER CONTROL:	<input type="checkbox"/>	<input type="checkbox"/>
CLEAN-UP COMPLETED:	<input type="checkbox"/>	<input type="checkbox"/>

TECHNICIAN:

TKM

DATE:

9 / 28 / 97

COMMENTS:

Clean closure

SITE Oak Summit FarmsREVIEW DATES 9/26/97

REGUST NONREG NONUST (circle)

REVIEWER TkmNA UST-12 FORMAT (closures 2/1/95 and after)☒ VOLUME OF UST (tnk1 10,000 tnk2 10,000 tnk3 270 tnk4 _____)☒ DIMENSIONS OF UST (tnk1 8' X 22' tnk2 12' X 14' tnk3 3' X 4' tnk4 _____)☒ MATERIAL STORED (tnk1 oil fuel tnk2 gasoline tnk3 wash oil tnk4 _____)☒ POTENTIAL RECEPTOR INFORMATION (closures 2/1/95 or after)☒ DEPTH OF TANK BURIAL 2' 13/1☒ SIDE OR FLOOR SAMPLE☒ DEPTH OF SAMPLE 18 1/8☒ HOW SAMPLE WAS COLLECTED (___ backhoe ☒ Auger ___ Grab)☒ SAMPLES PRESERVED & TRANSPORTED☒ SSE ACCEPTABLE☒ ANALYSIS METHOD 5030/3550 19071NA SEALED BY LG or PE (Needed for closures 1/1/94 - 7/1/96. After 7/1/96 a PG or PE is required only for sites that have a release or suspected release).

NAME/# OF SEALER _____

CONSULTING COMPANY _____

☒ USGS MAP☒ BASE MAP ☒ Orientation of UST ☒ APPROPRIATE SAMPLE LOCATIONS☒ REFERENCE TO SAMPLING POINT ON MAP ☒ CORRECT # OF TANK SAMPLES☒ PUMP SAMPLES☒ LINE SAMPLES☒ COMPLETE GW/UST-2 FORM (1/1/91 and after)☒ CLOSURE DATE 10/7/93☒ TANK DESTINATION Safeway Tank disposal (United metal recyclers)☒ SLUDGE DESTINATIONNA DISPOSITION OF SOIL☒ TIME/DATE SAMPLE COLLECTED☒ TIME/DATE LAB RECEIVED☒ CHAIN-OF-CUSTODY☒ WITHIN 14 DAY HOLDING TIME (or appropriate time)☒ LAB RESULTS☒ CERTIFIED LABORATORY USED (closures 8/1/93 and after)☒ Minor Soil _____ Major Soil _____ GW Violations

Comments: _____
